# **Before Use Fieldbus device** EX250-SDN1(-X102)

∕∕ SMC 

DeviceNet

Thank you for purchasing an SMC EX250-SDN1(-X102) Fieldbus device. Please read this manual carefully before operating the product and make sure you understand its capabilities and limitations. Please keep this manual handy for future reference

> To obtain the operation manual about this product and control unit, please refer to the SMC website (URL https://www.smcworld.com) or contact SMC directly

# **Safety Instructions**

These safety instructions are intended to prevent hazardous situations and/or equipment damage

These instructions indicate the level of potential hazard with the labels of "Caution", " Warning" or "Danger". They are all important notes for safety and must be followed in addition to International standards (ISO/IEC) and other safety regulations.



#### Operator

- This operation manual is intended for those who have knowledge of machinery using pneumatic equipment, and have sufficient knowledge of assembly. operation and maintenance of such equipment. Only those persons are allowed to perform assembly, operation and maintenance.
- Read and understand this operation manual carefully before assembling, operating or providing maintenance to the product.

#### ■Safety Instructions

Do not use for flammable or harmful fluids. Fire, malfunction, or damage to the product can result. Verify the specifications before use. Do not operate in an atmosphere containing flammable or explosive gases. Fire or an explosion can result. This product is not designed to be explosion proof. If using the product in an interlocking circuit: Provide a double interlocking system, for example a mechanical system. •Check the product regularly for proper operation. Otherwise malfunction can result, causing an accident. The following instructions must be followed during maintenance: •Turn off the power supply. •Stop the air supply, exhaust the residual pressure and verify that the air is released before performing maintenance. Otherwise an injury can result.	
Do not use for flammable or harmful fluids. Fire, malfunction, or damage to the product can result. Verify the specifications before use. Do not operate in an atmosphere containing flammable or explosive gases. Fire or an explosion can result. This product is not designed to be explosion proof. If using the product in an interlocking circuit: +Provide a double interlocking system, for example a mechanical system. -Check the product regularly for proper operation. Otherwise malfunction can result, causing an accident. The following instructions must be followed during maintenance: +Turn off the power supply. Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result. After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	An injury or failure can result.
Fire, malfunction, or damage to the product can result. Verify the specifications before use.	Do not operate the product outside of the specifications.
Verify the specifications before use.  Do not operate in an atmosphere containing flammable or explosive gases. Fire or an explosion can result. This product is not designed to be explosion proof.  If using the product in an interlocking circuit: Provide a double interlocking system, for example a mechanical system. Check the product regularly for proper operation. Otherwise malfunction can result, causing an accident.  Turn off the power supply. Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result.  After maintenance is complete, perform appropriate functional Inspections. Stop operation if the equipment does not function properly.	
Fire or an explosion can result. This product is not designed to be explosion proof.  If using the product in an interlocking circuit: -Provide a double interlocking system, for example a mechanical systemCheck the product regularly for proper operation. Otherwise malfunction can result, causing an accident.  The following instructions must be followed during maintenance: -Turn off the power supplyStop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result. <u>After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly. </u>	
This product is not designed to be explosion proof.  If using the product in an interlocking circuit:  Provide a double interlocking system, for example a mechanical system.  Check the product regularly for proper operation.  Otherwise malfunction can result, causing an accident.  The following instructions must be followed during maintenance:  Turn off the power supply.  Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance.  Otherwise an injury can result.  After maintenance is complete, perform appropriate functional inspections.  Stop operation if the equipment does not function properly.	
If using the product in an interlocking circuit: Provide a double interlocking system, for example a mechanical systemCheck the product regularly for proper operation. Otherwise malfunction can result, causing an accident.  The following instructions must be followed during maintenance: -Turn off the power supply. Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result.  After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	
-Provide a double interlocking system, for example a mechanical systemCheck the product regularly for proper operation. Otherwise malfunction can result, causing an accident.  Turn off the power supplyStop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result.  Caution After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	This product is not designed to be explosion proof.
Check the product regularly for proper operation. Otherwise malfunction can result, causing an accident.     Ime following instructions must be followed during maintenance:         -Turn off the power supply.     Stop the air supply, exhaust the residual pressure and verify that the air is released before performing maintenance.     Otherwise an injury can result.     Caution     After maintenance is complete, perform appropriate functional inspections.     Stop operation if the equipment does not function properly.	
Otherwise malfunction can result, causing an accident.  The following instructions must be followed during maintenance:  Turn off the power supply.  Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result.  Cher Caution After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	
The following instructions must be followed during maintenance:  Turn off the power supply.  Stop the air supply, exhaust the residual pressure and verify that the air is released before performing maintenance.  Otherwise an injury can result.   Curring Caution  After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	
• Turn off the power supply. • Stop the air supply, exhaust the residual pressure and verify that the air is released before performin maintenance. Otherwise an injury can result.    C Caution  After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	Otherwise mairunction can result, causing an accident.
Stop the air supply, exhaust the residual pressure and verify that the air is released before performing maintenance.     Otherwise an injury can result. <b>Caution</b> After maintenance is complete, perform appropriate functional inspections.     Stop operation if the equipment does not function properly.	
Maintenance. Otherwise an injury can result. <b>Caution</b> After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	
After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	
After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function properly.	maintonanoo.
After maintenance is complete, perform appropriate functional inspections. Stop operation if the equipment does not function property.	
Stop operation if the equipment does not function properly.	<b>△</b> Caution
	After maintenance is complete, perform appropriate functional inspections.
Safety cannot be assured in the case of unexpected malfunction.	Stop operation if the equipment does not function properly.
	Safety cannot be assured in the case of unexpected malfunction.

Individual grounding should be provided close to the product with a short cable

### ■NOTE

•When conformity to UL is necessary the SI unit must be used with a UL1310 Class 2 power supply.

•The product is a UL approved product only if it has a 🔊 mark on the body.

# Summary of Product elements



No.	Description	Function
1	Communication connector	Connect with DeviceNet® communication line.
2	Power supply connector	Supplies power to the solenoid valve, the Output block, SI unit and the Input block.
3	Input block connector	Connects the Input block.
4	Output block connector	Connects the solenoid valve, Output block and etc.
5	Display window	LED display shows the SI unit status.
6	Switch protective cover	Sets the address and baud rate etc. with the switch inside.
7	Grounding terminal (FE)	Used for grounding.

# Mounting and Installation

#### ■Installation

The SI unit does not have mounting holes, so it cannot be installed alone. Make sure to connect the valve manifold. When an input block is not required, connect the end plate directly to the SI unit

#### OAssembly and disassembly of the SI unit



#### Exchange of SI unit

•Remove screws from End Plate and release connection of each unit. Replace old SI unit with new one. (Tie-rod does not need to be removed.) ·Connect Input Block and End Plate and tighten removed screws by specified

tightening torque. (0.6 N•m)

Assembly and disconnection of unit Addition of Input Block

•Remove screws from End Plate. •Mount attached tie-rod.

 Connect additional Input Block.
 Connect End Plate and tighten removed screws by specified tightening torque. (0.6 N•m)

Caution for maintenance

(1) Be sure to turn-off all power supplies

(2) Be sure that there is no foreign object in any of units.

(3) Be sure that gasket is lined properly.

If these items are not kept, it may lead to the breakage of substrate or intrusion of

### ■Wiring

Communication wiring The DeviceNet<sup>®</sup> communication connector specifications are shown below

Communication connector

	<u>M12 5-pin</u>	plug A-code	
	No.	Description	Function
	1	DRAIN	Communication line ground/shield
50	2	V+	Power supply for DeviceNet <sup>e</sup> (+)
30 04	3	V-	Power supply for DeviceNet <sup>®</sup> (-)
	4	CAN_H	Communication line (High side)
	5	CAN_L	Communication line (Low side)

OPower supply wiring

Refer to "Safety Instructions" on this manual when selecting the power supply

## ·Power supply connector

	M12 5-pin	socket B-code	(reverse)
	No.	Description	Function
32	1	SV24 V	+24 V for valve
	2	SV0 V	0 V for valve
	3	SW24 V	+24 V for input
4 1	4	SW0 V	0 V for input
$\smile$	5	FE	Ground

### OFE connection

Connect the ground terminal to the ground. Resistance to the ground should be 100  $\Omega$  or less.

SW power is supplied to the sensor connected to the input block. There is a voltage drop up to maximum 1 V inside the SI unit when SW power is supplied. Select a sensor taking this voltage drop into consideration. If 24 V must be supplied to the sensor, it is necessar to increase the SW power supply voltage so that the input voltage of the sensor will be 24 V with the actual load. (Allowable SW power supply range: 19.2 V to 28.8 V)



#### O Terminating resistors

Example: PCA-1557675 etc. DeviceNet® requires a terminating resistor to be installed at each end of the trunk. The resistor requirements are:

•121 O

•1% metal film

•1/4 W

Terminating resistors should not be installed at the end of a drop line, only at the two ends of trunk line

# LED indication



LED	Description		
PWR(V)	Green LED is ON when power for solenoid valve is supplied.		
PWR	Green LED is ON when power for DeviceNet® communication is supplied.		
	OFF	Power supply is off, on-line status or checking for MAC ID duplication.	
	Green LED is flashing	I/O connection stand-by (on-line status)	
MOD/NET	Green LED is ON	I/O connection established (on-line status)	
	Red LED is flashing	I/O connection time-out (minor communication error) *	
	Red LED is ON	MAC ID duplication error or BUS OFF error (serious communication error)	

\*: EX250-SDN1 disconnects the I/O connection when the valve power supply decreases or when the input block fuse is detected to be broken (EX250-SDN1-X102 does not disconnect the I/O connection)

# Setting

OSwitch setting

Open the protective cover, and set the switches with a small flat blade screwdriver

- 1. The power supply should be off while setting the switches. 2. Be sure to set the switches before use.
- 3. After setting the switches, close the switch cover and tighten the screw to the
- specified torque. (Tightening torque: 0.6 N·m)

Address setting



Solenoid output state: Communication stops (I/O connection time out) or fault message is received.

SW1-9	-9 Solenoid output state		
1	HOLD	All solenoid valve outputs are hold before communication fault.	
0	CLEAR	All solenoid valve outputs are reset to zero.	

#### Modo sotti

	Mode set	tting
SW1-10 Mode		Mode
	0	H / W mode
	0	Set address and communication speed by SW1 to 8.
		S / W mode
	1	Set address and communication speed by network1.

# (4) Be sure that tightening torque is according to specification. liquid or dust into the units.

#### Output No. assignment Combinations of output data and valve manifold



- \*: Output No, starts from 0, and will be assigned to the valves in order from the SI unit mounted
- side. \*: Manifold wiring is double wired as standard ("double wiring specification"), and the output \*: Manifold wiring is double wired as standard ("double wiring specification"). numbers are assigned in order from A side to B side. If the mounted valves are single solenoid valves, the output on B side will be empty. (Refer to Fig. a)
- \*: Special wiring specification with a mixed wiring of single solenoid and double solenoid can be specified with a wiring specification sheet. This makes it possible to specify the output numbers
- without empty outputs. (Refer to Fig. b)
   Each bit status, 0 or 1, of the data shows the ON or OFF solenoid valve status (0: OFF, 1: ON), and the output number starting from 0 will be assigned to from the lowest bit of the memory data.



OInput No. assignment The inputs of the Input block are assigned from the SI unit side Input block in the order 0, 1, 2 ... maximum of 31.

# Troubleshooting

Technical documentation giving detailed troubleshooting information can be found on the SMC website (URL <a href="https://www.smcworld.com">https://www.smcworld.com</a>).

# Specifications

Power for DeviceNet®: 11 to 25 VDC, 0.1 A or less

Power for input: 24 VDC ±20%, 1 A or less (Depending on number of connecting sensors and specifications)

and specifications) Power for valve: 24 VDC +10%/-5%, 2 A or less (Depending on number of solenoid valve station and specifications) Connection load: Solenoid valve with protection circuit for 24 VDC and 1.5 W or less surge voltage. (made by SMC)

Operating ambient temp.: +5 to +45 °C Storage ambient temp.: -20 to +60 °C

\*1: Input terminal are not isolated from Power source \*2: Do not connect outside Power source to Input and Output terminals.

Technical documentation giving detailed specification information can be found on the SMC website (URL https://www.smcworld.com).

# **Outline Dimensions**

Technical documentation giving detailed outline dimensions information can be found on the SMC website (URL https://www.smcworld.com).

# Accessories

Technical documentation giving detailed accessories information can be found on the SMC website (URL https://www.smcworld.com)

SMC Corporation URL https://www.smcworld.com Akihabara UDX 15F, 4-14-1, Sotokanda, Chiyoda-ku, Tokyo 101-0021, JAPAN Phone: +81 3-5207-8249 Fax: +81 3-5298-5362

Note: Specifications are subject to change without prior notice and any obligation on the part of the manufacturer. DeviceNet\* is a registered trademark of ODVA, Inc. © 2011-2022 SMC Corporation All Rights Reserved EX%\*-OMP00