
## Are You Experiencing Water-Related Problems?

## Proposal for the Installation of Air Dryers

# Protect important equipment from water.








AIR DRYER

Decomposition of auto drain caused by rusting inside pipes

Stopping of machines

Generation of drain and outflow to the secondary side

### Component failure and frequent replacement Malfunctioning of valves and actuators caused by dripping grease



Water always accumulates in the filter...

The air used in the trial run of the device may have been dirty... Water flows from the device in summer...


The dryer is not being maintained...

Don't ignore the following!

An old dryer is being used...



#### We would like to propose a utility review.





Large dust particle filtration Water droplet separation Water droplet removal ratio: 99% Nominal filtration rating: 1 µm [Filtration efficiency: 99%]

